800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 16-03

December 18, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,EFFECTIVE UPON PUBLICATION Identified as follows: **AIRAC FDC FDC** STATE CITY **AIRPORT SUBJECT** DATE **NUMBER** DATE RNAV (GPS) RWY 28, 4-Feb-16 NC Statesville Statesville Rgnl 5/0906 12/07/15 Amdt 3

AIRAC Date: 4 February 2016

FDC **5/0906** SVH IAP STATESVILLE RGNL, STATESVILLE, NC. RNAV (GPS) RWY 28, AMDT 3... LPV DA 1167 ALL CATS. LNAV/VNAV DA 1218 ALL CATS. LNAV MDA/HAT 1300/333 ALL CATS. DELETE THRE 960 CHART TDZE 967. DELETE VDP AT 0.82 NM TO RWY 28. CHART VDP AT 0.89 NM TO RWY 28* *LNAV ONLY. DELETE FAS OBST: 1030 TREE 354546N/0805646W. CHART FAS OBST: 1042 TRMSN TWR 354614N/0805431W.

THIS IS RNAV (GPS) RWY 28, AMDT 3A. 1512022148-PERM